



Outside Ink Holdout

Inside Ink Holdout



- Please follow the exact die lines. It is important to keep the scale at 100%.
- It is essential that the grain run in the direction specified.
- The position of the envelope is critical to ensure proper treatment in the die cutting process. For best results, follow our layout.
- Minor variations may occur in the die cutting and folding process. Designs with bleed-through must wrap 1/8" around to back.
- The envelope machine cannot fold perfect borders or bleed-through. Designs with bleed-through must wrap 1/8" around to back.
- If you are running a full fold, please add gutter and color bar dimensions to the sheet size.
- Please mark your guide and gripper. Make sure the stock is logged.
- Knockout areas must be free of ink and varnish otherwise glue or gum may fail.
- Please call if you require special layout for products.

Thank you.



- Please follow the exact die lines. It is important to keep the scale at 100%.
- It is essential that the grain run in the direction specified.
- The position of the envelope is critical to ensure proper treatment in the die cutting process. For best results, follow our layout.
- Minor variations may occur in the die cutting and folding process. Designs with bleed-through must wrap 1/8" around to back.
- The envelope machine cannot fold perfect borders or bleed-through. Designs with bleed-through must wrap 1/8" around to back.
- If you are running a full fold, please add gutter and color bar dimensions to the sheet size.
- Please mark your guide and gripper. Make sure the stock is logged.
- Knockout areas must be free of ink and varnish otherwise glue or gum may fail.
- Please call if you require special layout for products.

Thank you.



- Please follow the exact die lines. It is important to keep the scale at 100%.
- It is essential that the grain run in the direction specified.
- The position of the envelope is critical to ensure proper treatment in the die cutting process. For best results, follow our layout.
- Minor variations may occur in the die cutting and folding process. Designs with bleed-through must wrap 1/8" around to back.
- The envelope machine cannot fold perfect borders or bleed-through. Designs with bleed-through must wrap 1/8" around to back.
- If you are running a full fold, please add gutter and color bar dimensions to the sheet size.
- Please mark your guide and gripper. Make sure the stock is logged.
- Knockout areas must be free of ink and varnish otherwise glue or gum may fail.
- Please call if you require special layout for products.

Thank you.



- Please follow the exact die lines. It is important to keep the scale at 100%.
- It is essential that the grain run in the direction specified.
- The position of the envelope is critical to ensure proper treatment in the die cutting process. For best results, follow our layout.
- Minor variations may occur in the die cutting and folding process. Designs with bleed-through must wrap 1/8" around to back.
- The envelope machine cannot fold perfect borders or bleed-through. Designs with bleed-through must wrap 1/8" around to back.
- If you are running a full fold, please add gutter and color bar dimensions to the sheet size.
- Please mark your guide and gripper. Make sure the stock is logged.
- Knockout areas must be free of ink and varnish otherwise glue or gum may fail.
- Please call if you require special layout for products.

Thank you.



- Please follow the exact die lines. It is important to keep the scale at 100%.
- It is essential that the grain run in the direction specified.
- The position of the envelope is critical to ensure proper treatment in the die cutting process. For best results, follow our layout.
- Minor variations may occur in the die cutting and folding process. Designs with bleed-through must wrap 1/8" around to back.
- The envelope machine cannot fold perfect borders or bleed-through. Designs with bleed-through must wrap 1/8" around to back.
- If you are running a full fold, please add gutter and color bar dimensions to the sheet size.
- Please mark your guide and gripper. Make sure the stock is logged.
- Knockout areas must be free of ink and varnish otherwise glue or gum may fail.
- Please call if you require special layout for products.

Thank you.